

# SEMIAT I

## USS WHIDBEY ISLAND (LSD 41)

### INTERNAL VIDEO VENTILATION ASSESSMENT



**PERFORMED BY  
SUPERVISOR OF SHIPBUILDING CONVERSION AND  
REPAIR**

**PORTSMOUTH, VIRGINIA**  
SUPSHIP: C. BUCK & QED: B. CAREW, R. DAVENPORT, B. PARSONS  
**17 THRU 28 JULY 2000**

## SUMMARY

A ventilation duct internal inspection was accomplished IAW the requirements of References (a) and (b), on board the USS WHIDBEY ISLAND (LSD 41) from 17 thru 28 July 2000, during a SEMAT I visit at NORSHIPCO, Norfolk, VA . The duct internal inspection determines the structural integrity (rust, wear, damage) and cleanliness (grease, dust, foreign matter) of the recirculation, exhaust and supply vent systems. Form 4790-2Ks were utilized to document discrepancies and were furnished for inclusion into the USS WHIDBEY ISLAND's Current Ship's Maintenance Project (CSMP). A proposed SUPSHIP, Portsmouth's Maintenance Repair Card (MRC), 5111-1 was used for the inspection criteria. The following pages have descriptions and pictures of the discrepancies discovered.

## REFERENCES

- a) COMNAVSURFLANT Continuous Maintenance Implementation /Improvement Policy Letter 09- Ventilation System Cleaning Policy Letter Ser N432A/1014 D dated 03 AUG 1999.
- b) COMNAVSURFLANT Message R091100Z Aug 1999 Shipboard Ventilation Cleaning Policy.




# VENT SYSTEM 01-128-1, EXHAUST

T/A 1  
SS03 P007  
STATUS 3  
PRI 2

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 01-128-1 IN COMPT.  
LAUNDRY FINISHING ROOM (2-129-1-Q) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 01-128-1 IN COMPT.  
LAUNDRY FINISHING ROOM (2-129-1-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

## LAUNDRY FINISHING ROOM (2-129-1-Q)



3 FT Inside Duct Looking Forward (Foreign material)

## LAUNDRY & DRY CLEANING ROOM (2-121-1-Q)



1 FT Inside Duct By The Back Of Dryers (Foreign material)

# VENT SYSTEM


## 01-14-2, RECIRC RETURN

T/A 1  
OW01 P001  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 01-14-2 IN COMPT.  
Passageway (02-20-1-L) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 01-14-2 IN COMPT.  
Passageway (02-20-1-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGEWAY (02-20-1-L)



10 FT Inside Duct (Foreign material)

PASSAGEWAY (02-20-1-L)



5 FT Inside Duct (Foreign material)

# VENT SYSTEM


## 01-20-2, EXHAUST

T/A 1  
EE01 P805  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 01-20-2 IN COMPT.  
DECK WR & WC (01-27-6-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 01-20-2 IN COMPT.  
DECK WR & WC (01-27-6-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

DECK WR & WC (01-27-6-L)



15 FT Inside Duct (Foreign material)

DECK WR & WC (01-27-6-L)



8 FT Inside Duct (Foreign material)


# VENT SYSTEM 01-33-1, EXHAUST

T/A 1  
ER03 P001  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 01-33-1 IN COMPT.  
FILTER CLEANING SHOP (01-29-7-Q) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 01-33-1 IN COMPT.  
FILTER CLEANING SHOP (01-29-7-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

FILTER CLEANING SHOP (01-29-7-Q)



10 FT Inside Duct (Foreign material)

FILTER CLEANING SHOP (01-29-7-Q)



15 FT Inside Duct (Foreign material)


# VENT SYSTEM 01-34-1, EXHAUST

T/A 1  
EE01 P802  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 01-34-1 IN COMPT.  
ELEVATOR MCHRY ROOM (01-27-1-Q) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 01-34-1 IN COMPT.  
ELEVATOR MCHRY ROOM (01-27-1-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

ELEVATOR MCHRY ROOM (01-27-1-Q)



10 FT Inside Duct (Foreign material)

ELEVATOR MCHRY ROOM (01-27-1-Q)



5 FT Inside Duct (Foreign material)


# VENT SYSTEM 01-52-2, SUPPLY

T/A 1  
ER02 P661  
STATUS 3  
PRI 3

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 01-52-2 IN COMPT.  
CARPENTER SHOP (01-52-2-Q) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 01-52-2 IN COMPT.  
CARPENTER SHOP (01-52-2-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

CARPENTER SHOP (01-52-2-Q)



2 FT Inside Duct (Foreign material)

CARPENTER SHOP (01-52-2-Q)



10 FT Inside Duct (Foreign material)


# VENT SYSTEM 01-59-1, EXHAUST

T/A 1  
SS01 P011  
STATUS 3  
PRI 2

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 01-59-1 IN COMPT.  
PASSAGE (01-43-3-L) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 01-59-1 IN COMPT.  
PASSAGE (01-43-3-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGE (01-43-3-L)



2 FT Inside Duct At FR 53 (Foreign material)

# VENT SYSTEM


## 02-14-1, EXHAUST

T/A 1  
SS02 P6.03  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 02-14-1 IN COMPT. CO Bath (06-29-2-L) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 02-14-1 IN COMPT. CO Bath (06-29-2-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

CO Bath (06-29-2-L)



1 FT Inside Duct (Foreign material)

TROOP WR & WC (02-26-0-L)



2 FT Inside Duct (Foreign material)

# VENT SYSTEM


## 02-38-2, RECIRC RETURN

T/A 1  
MH01 P016  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 02-38-2 IN COMPT. MEDICAL OPERATING ROOM (02-43-2-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 02-38-2 IN COMPT. MEDICAL OPERATING ROOM (02-43-2-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

MEDICAL OPERATING ROOM (02-43-2-L)



5 FT Inside Duct (Foreign material)

MEDICAL OPERATING ROOM (02-43-2-L)



3 FT Inside Duct (Foreign material)


# VENT SYSTEM 02-47-2, SUPPLY

T/A 1  
EM08 P022  
STATUS 3  
PRI 2

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 02-47-2 IN COMPT.  
AUX MCHRY ROOM NO. 1 (5-43-0-E) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 02-47-2 IN COMPT.  
AUX MCHRY ROOM NO. 1 (5-43-0-E) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

AUX MCHRY ROOM NO. 1 (5-43-0-E)



15 FT Inside Duct At FR 45 (Foreign material)

AUX MCHRY ROOM NO. 1 (5-43-0-E))



12 FT Inside Duct At FR 46 (Foreign material)

# VENT SYSTEM


## 02-61-2, RECIRC RETURN

T/A 1  
MH01 P015  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 02-61-2 IN COMPT.  
SURGICAL DRESSING ROOM & MAIN BDS (02-48-2-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 02-61-2 IN COMPT.  
SURGICAL DRESSING ROOM & MAIN BDS (02-48-2-L) IN ITS ENTIRETY THEN RESTORE TO  
NORMAL OPERATION.

### SURGICAL DRESSING ROOM & MAIN BDS (02-48-2-L)



3 FT Inside Duct (Foreign material)

### SURGICAL DRESSING ROOM & MAIN BDS (02-48-2-L)



5 FT Inside Duct (Foreign material)


# VENT SYSTEM 02-61-4, EXHAUST

T/A 1  
MH01 P014  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 02-61-4 IN COMPT. WARD BATH (02-56-2-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 02-61-4 IN COMPT. WARD BATH (02-56-2-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

WARD BATH (02-56-2-L)



3 FT Inside Duct (Foreign material)

WARD BATH (02-56-2-L)



6 FT Inside Duct (Foreign material)

# VENT SYSTEM 03-61-3, EXHAUST

T/A 1  
SS02 P606  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 03-61-3 IN COMPT. GALLEY (03-37-0-Q) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 03-61-3 IN COMPT. GALLEY (03-37-0-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

GALLEY (03-37-0-Q)



4 FT Inside Duct Looking Toward Deep Fat Fryers (Foreign material)

GALLEY (03-37-0-Q)



1 FT Inside Duct Looking Up Vent Hood Over STEAM IT (Foreign material)

# VENT SYSTEM


## 04-23-1, RECIRC RETURN

T/A 1  
DA01 P901  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 04-23-1 IN COMPT. PASSAGEWAY (04-21-1-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 04-23-1 IN COMPT. PASSAGEWAY (04-21-1-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGEWAY (04-21-1-L)



2 FT Inside Duct (Foreign material)

PASSAGEWAY (04-21-1-L)



4 FT Inside Duct (Foreign material)

# VENT SYSTEM

## 04-29-2, EXHAUST


T/A 1  
SS02 P607

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 04-29-2 IN COMPT. WARDROOM, CPO, SR TROOP NCO SCULLERY (03-34-2-Q) IS DIRTY AND REQUIRES CLEANING.

STATUS 3  
PRI 3

REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 04-29-2 IN COMPT. WARDROOM, CPO, SR TROOP NCO SCULLERY (03-34-2-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

WARDROOM, CPO, SR TROOP NCO SCULLERY (03-34-2-Q)



1 FT Inside Duct Looking Up Vent Hood Over Dishwasher (Foreign material)

# VENT SYSTEM


## 04-43-1, RECIRC RETURN

T/A 1  
OC01 P602  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 04-43-1 IN COMPT. COMMUNICATION CENTER (04-30-0-C) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 04-43-1 IN COMPT. COMMUNICATION CENTER (04-30-0-C) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

COMMUNICATION CENTER (04-30-0-C)



10 FT Inside Duct (Foreign material)

COMMUNICATION CENTER (04-30-0-C)



4 FT Inside Duct (Foreign material)

# VENT SYSTEM


## 04-54-1, RECIRC RETURN

T/A 1  
ER01 P803  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 04-54-1 IN COMPT.  
PASSAGEWAY (04-52-2-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT SYSTEM R 04-54-1 IN COMPT.  
Passageway (04-52-2-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGEWAY (04-52-2-L)



3 FT Inside Duct (Foreign material)

PASSAGEWAY (04-52-2-L)



10 FT Inside Duct (Foreign material)


# VENT SYSTEM 04-54-2, EXHAUST

T/A 1  
ER01 P804  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 04-54-2 IN COMPT. CREW WR & WC (03-52-6-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 04-54-2 IN COMPT. CREW WR & WC (04-52-4-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

CREW WR & WC (04-52-4-L)



3 FT Inside Duct (Foreign material)

CREW WR & WC (04-52-4-L)



5 FT Inside Duct (Foreign material)


# VENT SYSTEM 04-54-4, EXHAUST

T/A 1  
SS03 P005  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC EXHAUST DUCT, SYSTEM E 04-54-4 IN COMPT. PASSAGE (03-52-6-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 04-54-4 IN COMPT. PASSAGE (03-52-6-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGEWAY (03-52-6-L)



2 FT Inside Duct (Foreign material)

SCULLERY (03-43-2-Q)



8 FT Inside Duct (Foreign material)

# VENT SYSTEM


## 05-51-2, RECIRC RETURN

T/A 1  
OI01 P206  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 05-51-2 IN COMPT. PASSAGE (05-48-0-L) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 05-51-2 IN COMPT. PASSAGE (05-48-0-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGEWAY (05-48-0-L)



1 FT Inside Duct Looking Towards Fan Room (Foreign material)

# VENT SYSTEM


## 05-51-4, RECIRC RETURN

T/A 1  
OI01 P205  
STATUS 3  
PRI 3

As per Internal Video Inspection: RECIRC RETURN DUCT, SYSTEM R 05-51-4 IN COMPT.  
Passageway (05-48-0-L) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN RECIRC RETURN DUCT, SYSTEM R 05-51-4 IN COMPT.  
Passageway (05-48-0-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

PASSAGEWAY (05-48-0-L)



Inside Duct Looking Toward Fan Room (Foreign material)

# VENT SYSTEM


## 06-38-2, EXHAUST

T/A 1  
SS02 P604  
STATUS 3  
PRI 3

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 06-38-2 IN COMPT. OFFICER SHOWER & DRYING (06-31-5-L) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 06-38-2 IN COMPT. OFFICER SHOWER & DRYING (06-31-5-L) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

OFFICER SHOWER & DRYING (06-31-5-L)



5 FT Inside Duct (Foreign material)

CPO & SR Troop NCO WR & WC (05-35-5-L)



2 FT Inside Duct (Foreign material)


# VENT SYSTEM 1-118-1, SUPPLY

T/A 1  
SS03 P008  
STATUS 3  
PRI 2

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 1-118-1 IN COMPT.  
LAUNDRY RCVG & ISSUE (2-115-1-Q) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 1-118-1 IN COMPT.  
LAUNDRY RCVG & ISSUE (2-115-1-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

LAUNDRY RCVG & ISSUE (2-115-1-Q)



1 FT Inside Duct Looking Aft (Foreign material)

LAUNDRY & DRY CLEANING ROOM (2-121-1-Q)



2 FT Inside Duct (Foreign material)


# VENT SYSTEM 1-52-1, SUPPLY

T/A 1  
EM01 P021  
STATUS 3  
PRI 2

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 1-52-1 IN COMPT.  
MAIN MCHRY ROOM NO. 1 (5-52-0-E) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 1-52-1 IN COMPT.  
MAIN MCHRY ROOM NO. 1 (5-52-0-E) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

MAIN MCHRY ROOM NO. 1 (5-52-0-E)



4 FT Inside Duct At FR 54 (Foreign material)

MAIN MCHRY ROOM NO. 1 (5-52-0-E)



8 FT Inside Duct At FR 54 (Foreign material)


# VENT SYSTEM 1-60-2, SUPPLY

T/A 1  
EM01 P022  
STATUS 3  
PRI 2

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 1-60-2 IN COMPT.  
MAIN MCHRY ROOM NO. 1 (5-52-0-E) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 1-60-2 IN COMPT.  
MAIN MCHRY ROOM NO. 1 (5-52-0-E) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

MAIN MCHRY ROOM NO. 1 (5-52-0-E)



3 FT Inside Duct At FR 63 (Foreign material)

MAIN MCHRY ROOM NO. 1 (5-52-0-E)



6 FT Inside Duct At FR 63 (Foreign material)


# VENT SYSTEM 1-80-2, SUPPLY

T/A 1  
EM02 P009  
STATUS 3  
PRI 2

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 1-80-2 IN COMPT.  
MAIN MCHRY ROOM NO. 2 (5-74-0-E) IS DIRTY AND REQUIRES CLEANING.

REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 1-80-2 IN COMPT.  
MAIN MCHRY ROOM NO. 2 (5-74-0-E) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

MAIN MCHRY ROOM NO. 2 (5-74-0-E)



3 FT Inside Duct At FR 74 (Foreign material)

MAIN MCHRY ROOM NO. 2 (5-74-0-E)



12 FT Inside Duct At FR 74 (Foreign material)

# VENT SYSTEM 1-85-1, SUPPLY

T/A 1  
EM02 P008  
STATUS 3  
PRI 2

As per Internal Video Inspection: SUPPLY DUCT, SYSTEM S 1-85-1 IN COMPT.  
MAIN MCHRY ROOM NO. 2 (5-74-0-E) IS DIRTY AND REQUIRES CLEANING.


REPAIR ACTIVITY OPEN AND CLEAN SUPPLY DUCT, SYSTEM S 1-85-1 IN COMPT.  
MAIN MCHRY ROOM NO. 2 (5-74-0-E) IN ITS ENTIRETY THEN RESTORE TO NORMAL  
OPERATION.

MAIN MCHRY ROOM NO. 2 (5-74-0-E)



6 FT Inside Duct At FR 87 (Foreign material)

MAIN MCHRY ROOM NO. 2 (5-74-0-E)



3 FT Inside Duct At FR 87 (Foreign material)

# VENT SYSTEM

## 2-109-1, EXHAUST


T/A 1  
SS03 P006

As per Internal Video Inspection: EXHAUST DUCT, SYSTEM E 2-109-1 IN COMPT. INCLUDING DUCTING FROM DRYERS IN COMPT. LAUNDRY (SELF-SERVICE) (2-111-1-Q) IS DIRTY AND REQUIRES CLEANING.

STATUS 3  
PRI 2


REPAIR ACTIVITY OPEN AND CLEAN EXHAUST DUCT, SYSTEM E 2-109-1 IN COMPT. INCLUDING DUCTING FROM DRYERS IN COMPT. LAUNDRY (SELF-SERVICE) (2-111-1-Q) IN ITS ENTIRETY THEN RESTORE TO NORMAL OPERATION.

LAUNDRY (SELF-SERVICE) (2-111-1-Q)



8 FT Inside Duct Looking Toward Fan Room (Foreign material)

LAUNDRY (SELF-SERVICE) (2-111-1-Q)



1 FT Inside Duct From Dryers (Foreign material)